

PYROTECHNIC DEVICES ACTIVE (HANDLING DAMAGE)
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

TABLE OF CONTENTS

| PROBLEM NUMBER | DESCRIPTION | PAGE NUMBER |
|-----------------|--|-------------|
| <u>INDEXES</u> | | |
| | EQUIPMENT INDEX | ii |
| | ACTION INDEX | iii |
| | ORIGINATORS INDEX | iv |
| | DUE DATE SUMMARY | v |
| PROBLEMS | | |
| <u>16902</u> | DURING ISSUE INSPECTION MK 58 MOD 1 MARINE LOCATION MARKER HAD .. GOUGES..... | 1 |

NOTE: OPEN problems denoted by asterisk (*) following problem number.

30-NOV-01

PYROTECHNIC DEVICES ACTIVE (HANDLING DAMAGE)
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 16902 CLOSED

| | NOMENCLATURE | PART/DOC. NO. | FSC | NIIN | NALC |
|------------|--------------------------|---------------|------|-------------|------|
| END ITEM : | MARKER, LOCATION, MARINE | 2141502 | 1370 | 00-794-4594 | L585 |

EI CNTRL NO:

PROB BRIEF : DURING ISSUE INSPECTION MK 58 MOD 1 MARINE LOCATION MARKER HAD GOUGES

PROBLEM : Discovered gouges on marker while issuing MK 58 MOD 1 Marine
DESCRIPTION Location Marker to squadron personnel.

PREVENTIVE : None.
ACTION

CORRECTIVE : None.
ACTION

| | SOURCE | TYPE | DOCUMENT NO. | DATE | DR STATUS |
|--------------|----------------------|------|----------------|---------|-----------|
| OCCURRENCES: | USS LINCOLN (CVN-72) | CODR | R21297-00-0830 | 06DEC00 | CLOSED |

ACTION : USS LINCOLN (CVN-72) CODR R21297-00-0830 06DEC00 CLOSED

| | PART/DOC. NO. | FSC | NIIN | NALC |
|--------------|---------------------------------|------|-------------|------|
| END ITEM : | 2141502 | 1370 | 00-794-4594 | L585 |
| | NOMEN: MARKER, LOCATION, MARINE | | | |
| | LOT: CRA87M010-001 | | | |
| FAILED PART: | 2141502 | 1370 | 00-794-4594 | L585 |
| | NOMEN: MARKER, LOCATION, MARINE | | | |

DESCRIPTION:

06DEC00: Crew members of USS Abraham Lincoln (CVN-72) discovered a gouge measuring two inches long by one half inch wide on marker while issuing MK 58 Mod 1 Marine Location Marker to squadron personnel from jettison locker number two. The gouge was deep enough to expose white phosphorus. The flight deck supervisor notified ordnance control to obtain permission to jettison marker overboard. Permission was granted and the marine location marker was jettisoned overboard per NAVSEA SWO050-B-MMA-010, Chapter 22, Page 11-26, paragraph 11-2.5.10. It is suspected that the Marine Location Marker was damaged prior to stowage in jettison locker. Also noted that G-1 Flight Deck Personnel failed to perform proper weapons inspection during return issue from squadron.

ACTION TAKEN:

28DEC00: Reporting activity was notified by NAVSURFWARCENDIV Crane that the problem had been entered for tracking purposes only. No further action would be taken. NAVSURFWARCENDIV Crane will continue to monitor expenditures of MK-58 MLMS. This incident is considered closed.

30-NOV-01

PYROTECHNIC DEVICES ACTIVE (HANDLING DAMAGE)
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 16902

(Continued) |

| ACTION | : ACTIVITY/CODE | ASSIGNMENT | DUE DATE | STATUS |
|---------|-----------------|-----------------|----------|------------------|
| SUMMARY | NSWC CRANE/4022 | REVIEW INCIDENT | | COMPLETE 28DEC00 |

| REFERENCES | : IDENTIFICATION | REFERENCE BRIEF |
|------------|--|-------------------|
| | USS LINCOLN (CVN-72) MESSAGE 062044ZDEC00 | REPORTED INCIDENT |
| | NSWC CRANE/4022 MESSAGE 281931ZDEC00 | CLOSING ACTION |