

**MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM**

TABLE OF CONTENTS

PROBLEM NUMBER	DESCRIPTION	PAGE NUMBER
<u>INDEXES</u>		
	EQUIPMENT INDEX	ii
	ACTION INDEX	iv
	ORIGINATORS INDEX	vi
	DUE DATE SUMMARY	xii
 PROBLEMS		
<u>14887</u>	NO VIDEO/IR COOLING.....	1
<u>14892</u>	MISSILE FAILED TO IDENT ON AIRCRAFT.....	20
<u>14893</u>	MISSILE FAILED TO CAGE.....	22
<u>14981</u>	SAFE AND ARM MECHANISM SUSPECTED OUT OF ALIGNMENT.....	24
<u>15044</u>	FAILURE TO SLEW PROPERLY.....	26
<u>15436</u>	MISSILE FAILED TO LOCK ON TARGET LOADED ON AIRCRAFT.....	29
<u>15502</u>	MISSILE FAILED TO FIRE.....	31
<u>15594*</u>	MISSILE FAILED TO FUNCTION PROPERLY WHEN LAUNCHED.....	34
<u>15694</u>	GUIDANCE AND CONTROL SECTION FAILURE, NO VIDEO.....	37
<u>16229</u>	LEAKING FLUID FROM HYDRAULIC ACTUATION SYSTEM.....	39
<u>16251</u>	NO DISPLAY SYMBOLOGY.....	41
<u>16304</u>	FAILED IN FLIGHT.....	43
<u>16382</u>	MISSILE FAILED TO DETONATE.....	45
<u>16462</u>	MISSILE JETTISONED DUE TO USAFE LANDING GEAR ON F-18.....	47
<u>16742</u>	HYDRAULIC ACTUATOR FILL INDICATOR SERVICING.....	49
<u>16868</u>	MISSILE BROKE LOCK ON LAUNCH.....	51
<u>16897</u>	BRACKET FOR UMBILICAL CONNECTION BROKEN.....	52

NOTE: OPEN problems denoted by asterisk (*) following problem number.

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 14887 CLOSED

END ITEM	NOMENCLATURE	PART/DOC. NO.	FSC	NIIN	NALC
:	GUIDED MISSILE, MAVERICK	3384304-101	1410	01-158-2872	PB69
	GUIDED MISSILE, TRAINING	3384305-100	6290	01-254-7577	3W70
	GUIDED MISSILE, MAVERICK	3384305-101	6920	01-238-0123	3W70
	GUIDED MISSILE, MAVERICK	3647135-100	1410	01-253-8073	PD63
	GUIDED MISSILE, MAVERICK	3647136-100	6920	01-254-7577	PY15

EI CNTRL NO:

PROB BRIEF : NO VIDEO/IR COOLING

PROBLEM : Missiles fail video checks on aircraft.
DESCRIPTION

PREVENTIVE : There is no preventive action.
ACTION

CORRECTIVE : When ECP 993 (Signal Processor Unit modification) is approved, the
ACTION video problem with the TGM-65E, and the CATM-65F will be resolved. Anticipated approval of ECP is March 1993. All tactical missiles listed in this category are considered true failures. As additional information becomes available, an update will be provided. The TTU-519/E MAVERICK missile test set will not detect video problems with training missiles. Notify NAWCWPNS before processing any MAVERICK Training assets reported to have video problems in order to preclude faulty missiles being returned for fleet use.

OCCURRENCES:	SOURCE	TYPE	DOCUMENT NO.	DATE	DR STATUS
	VMA-214	CODR	M09436-01-0044	11OCT01	CLOSED
	VMA-214	CODR	M09436-01-0035	26SEP01	CLOSED
	VMA-513	CODR	M09231-01-0028	25SEP01	CLOSED
	VMA-231	CODR	M52948-01-0035	05SEP01	CLOSED
	VFA-27	CODR	R65185-01-0008	24AUG01	CLOSED
	VMFA-323	CODR	M09235-01-0028	02AUG01	CLOSED
	VMA-513	CODR	M09231-01-0017	08JUN01	CLOSED
	VP-1	CODR	R09618-01-0024	04JUN01	CLOSED
	VFA-27	CODR	R65185-01-0003	15MAY01	CLOSED
	VFA-137	CODR	V55142-01-0020	06MAY01	CLOSED
	VFA-105	CODR	V65183-01-0016	08APR01	CLOSED
	VFA-37	CODR	V09478-01-0027	24MAR01	CLOSED
	VP-26	CODR	V09610-01-0007	12MAR01	CLOSED
	VMA-542	CODR	M52847-01-0009	27FEB01	CLOSED
	VS-22	CODR	V09287-01-0010	25FEB01	CLOSED
	VP-26	CODR	V09610-00-0001	09FEB01	CLOSED
	VP-45	CODR	V09665-00-0028	23DEC00	CLOSED
	VMFA-312	CODR	M09253-00-0020	07NOV00	CLOSED
	VFA-195	CODR	R09706-00-0048	06NOV00	CLOSED
	VFA-83	CODR	V09223-00-0027	24OCT00	CLOSED
	VP-45	CODR	V09665-00-0023	06OCT00	CLOSED

**MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM**

PROBLEM NO: 14887

(Continued)

SOURCE	TYPE	DOCUMENT NO.	DATE	DR STATUS
VP-45	CODR	V09665-00-0024	06OCT00	CLOSED
VP-45	CODR	V09665-00-0017	21SEP00	CLOSED
VFA-25	CODR	R09637-00-0015	28JUN00	CLOSED *
VFA-27	CODR	R65185-00-0014	18MAY00	CLOSED *
NSF DIEGO GARCIA	CODR	N68539-00-0003	10MAY00	CLOSED *
VFA-34	CODR	V09070-00-0003	17APR00	CLOSED *
VP-5	CODR	V09630-00-0005	10APR00	CLOSED *
VMFA(AW)-533	CODR	M09193-00-0003	21MAR00	CLOSED *
VFA-81	CODR	V09221-00-0008	08FEB00	CLOSED *
VFA-83	CODR	V09223-00-0001	25JAN00	CLOSED *
VP-8	CODR	V09661-99-0030	17DEC99	CLOSED *
VP-16	CODR/EIR	V09229-99-0034	17NOV99	CLOSED *
VMFA(AW)-225	CODR	M09232-99-0048	02NOV99	CLOSED *
VP-16	CODR	V09229-99-0030	25OCT99	CLOSED *
VP-1	CODR	R09618-99-0013	23OCT99	CLOSED *
VFA-137	CODR	V55142-99-0075	22OCT99	CLOSED *
VFA-131	CODR	R63934-99-0020	21OCT99	CLOSED *
VMA-223	CODR	M09438-99-0032	04OCT99	CLOSED *
VP-9	CODR	R09644-99-0021	24SEP99	CLOSED *
VFA-147	CODR	R63925-99-0018A	20AUG99	CLOSED *
VMA-214	CODR	M09436-99-0004	28JUN99	CLOSED *
VFA-131	CODR	R63934-99-0010	25JUN99	CLOSED *
VMA-513	CODR	M09231-99-0018	10JUN99	CLOSED *
VMA-542	CODR	M52847-99-0052	02JUN99	CLOSED *
VMFA-312	CODR	M09253-99-0015	07APR99	CLOSED *
VFA-192	CODR	R09076-99-0005	05MAR99	CLOSED *
VFA-115	CODR	R09604-99-0005	03MAR99	CLOSED *
VP-1	CODR	R09618-99-0001	15JAN99	CLOSED *
VS-22	CODR	V09287-98-0021	28NOV98	CLOSED *
VP-10	CODR	V09639-98-0030	20OCT98	CLOSED *
VFA-34	CODR	V09070-98-0033	14OCT98	CLOSED *
VP-9	CODR	R09644-98-0018	01OCT98	CLOSED *
VMFA-312	CODR	M09253-98-0025	16AUG98	CLOSED *
VFA-94	CODR	R09295-98-0037	06AUG98	CLOSED *
VFA-115	CODR	R09604-98-0038	31JUL98	CLOSED *
VS-30	CODR	V09226-98-0008	04JUN98	CLOSED *
MAWTS-1	CODR	M55167-98-0010	20APR98	CLOSED *
VFA-131	CODR	R63934-98-0010	06APR98	CLOSED *
VP-47	CODR	R09600-98-0005	07MAR98	CLOSED *
VP-47	CODR	R09600-98-0004	15FEB98	CLOSED *
VP-47	CODR	R09600-98-0003	10FEB98	CLOSED *
VFA-27	CODR	R65185-98-0002	16JAN98	CLOSED *
VMFA(AW)-225	CODR	M09232-97-0036	07JAN98	CLOSED *
VFA-82	CODR	V09122-97-0060	17NOV97	CLOSED *

* ACTION REPORTED IN PREVIOUS PUBLICATION

**MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM**

PROBLEM NO: 14887

(Continued)

SOURCE	TYPE	DOCUMENT NO.	DATE	DR STATUS
VP-4	CODR	R09623-97-0018	02OCT97	CLOSED *
VFA-82	CODR	V09122-97-0046	25SEP97	CLOSED *
VP-40	CODR	R09674-97-0028	24SEP97	CLOSED *
VFA-146	CODR	R09063-97-0023	13SEP97	CLOSED *
VFA-87	CODR	V63922-97-0016	12SEP97	CLOSED *
VMFA(AW)-332	CODR	M09501-97-0018	18AUG97	CLOSED *
VFA-151	CODR	R09558-97-0039	15AUG97	CLOSED *
VFA-27	CODR	R65185-97-0037	07AUG97	CLOSED *
VFA-137	CODR	V55142-97-0017	15JUN97	CLOSED *
VFA-151	CODR	R09558-97-0025	15JUN97	CLOSED *
VFA-137	CODR	V55142-97-0015	14JUN97	CLOSED *
VP-9	CODR	R09644-97-0007	07MAY97	CLOSED *
VP-9	CODR	R09644-97-0005	21APR97	CLOSED *
VFA-87	CODR	V63922-97-0010	17MAR97	CLOSED *
VP-9	CODR	R09644-97-0002	05MAR97	CLOSED *
VFA-137	CODR	V55142-97-0005	16FEB97	CLOSED *
VMFA(AW)-242	CODR	M09668-96-0023	09AUG96	CLOSED *
VA-75	CODR	V09628-96-0104	08MAY96	CLOSED *
MAWTS-1	CODR	M55167-96-0015	27MAR96	CLOSED *
VA-75	CODR	V09628-96-0102	21MAR96	CLOSED *
VFA-136	CODR	V55141-96-0008	17FEB96	CLOSED *
VFA-22	CODR	R09561-96-0016	07FEB96	CLOSED *
VFA-27	CODR	R65185-95-0037	15NOV95	CLOSED *
VFA-37	CODR	V09478-95-0044	22OCT95	CLOSED *
MAWTS-1	CODR	M55167-95-0024	19OCT95	CLOSED *
VP-8	CODR	V09661-95-0014	12OCT95	CLOSED *
VA-115	CODR	R09604-95-0034	05OCT95	CLOSED *
VMA-513	CODR	M09231-95-0018	13JUL95	CLOSED *
VA-128	CODR	R09522-95-0017	11JUL95	CANCELED*
VA-128	CODR	R09522-95-0014	24MAY95	CLOSED *
NSWC FALLON	CODR/EIR	N68847-95-0023	21APR95	CLOSED *
VMFA-251	CODR	M09241-95-0006	28MAR95	CLOSED *
NSWC FALLON	CODR	N68847-95-0015	20MAR95	CLOSED *
VFA-37	CODR	V09478-95-0012	23FEB95	CLOSED *
VFA-22	CODR/EIR	R09561-95-0005	06FEB95	CLOSED *
VFA-22	CODR/EIR	R09561-95-0006	06FEB95	CLOSED *
VMA-311	CODR	M09416-94-0033	28DEC94	CLOSED *
VMA-211	CODR	M09412-94-0047	14SEP94	CLOSED *
NWS YORKTOWN	PQDR II	N00109-94-3130	06SEP94	CLOSED *
VFA-105	CODR	V65183-94-0022	25AUG94	CLOSED *
NWS YORKTOWN	PQDR II	N00109-94-3124	18AUG94	CLOSED *
NWS YORKTOWN	PQDR II	N00109-94-3126	18AUG94	CLOSED *
VFA-37	CODR	V09478-94-0051	15AUG94	CLOSED *
VMFA(AW)-225	CODR	M09232-94-0022	19JUL94	CANCELED*

* ACTION REPORTED IN PREVIOUS PUBLICATION

**MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM**

PROBLEM NO: 14887 (Continued)

SOURCE	TYPE	DOCUMENT NO.	DATE	DR STATUS
VFA-25	CODR	R09637-94-0044	09JUN94	CLOSED *
VA-165	CODR	R09616-94-0018	07MAY94	CLOSED *
VP-23	CODR	V09043-94-0004	17MAR94	CLOSED *
VMFA(AW)-225	CODR	M09232-94-0003	16FEB94	CLOSED *
VFA-94	CODR	R09295-94-0003	27JAN94	CLOSED *
VA-75	CODR/EMR	V09628-94-0001	09JAN94	CLOSED *
VP-26	CODR	V09610-93-0038	21DEC93	CLOSED *
VMFA(AW)-242	CODR	M09668-93-0031	13AUG93	CLOSED *
VMFA(AW)-225	CODR	M09232-93-0016	23APR93	CLOSED *
VA-36	CODR	V09941-93-0010	05APR93	CLOSED *
VFA-131	EMR	R63934-93-0022	12MAR93	CLOSED *
VA-34	CODR	V09070-93-0006	12FEB93	CLOSED *
VA-75	EMR	V09628-93-0008	01FEB93	CLOSED *
VA-34	EMR	V09070-93-0001	06JAN93	CLOSED *
VA-35	EMR	V09728-92-0064	22DEC92	CLOSED *
VA-35	EMR	V09728-92-0065	22DEC92	CLOSED *
VA-65	EMR	V09710-92-0096	21DEC92	CLOSED *
VA-75	EMR	V09628-92-0045	09DEC92	CLOSED *
VFA-105	EMR	V65183-92-0022	13NOV92	CLOSED *
VA-75	EMR	V09628-92-0037	28OCT92	CLOSED *
VA-35	EMR	V09728-92-0039	18JUL92	CLOSED *
VA-145	EMR	R09284-92-0049	10JUL92	CLOSED *
VFA-192	EMR	R09076-92-0023	28MAY92	CLOSED *
VA-65	EMR	V09710-92-0041	10APR92	CLOSED *
VA-65	EMR	V09710-92-0028	13MAR92	CLOSED *
VA-34	EMR	V09070-91-0085	15DEC91	CLOSED *
VFA-131	EMR	R63934-91-0048	05NOV91	CLOSED *
VMFA(AW)-242	EMR	M09668-91-0059	21OCT91	CLOSED *

* ACTION REPORTED IN PREVIOUS PUBLICATION

ACTION : VMA-214 CODR M09436-01-0044 11OCT01 CLOSED

END ITEM : PART/DOC. NO. FSC NIIN NALC
FAILED PART: S/N: 6100394
 3647136-100 6920 01-254-7577 PY15
NOMEN: GUIDED MISSILE, MAVERICK

DESCRIPTION:

24SEP01: VMA-214 reported that ordnance personnel performed weapons systems checks and loaded aircraft with captive CATM-65F. Crew proceeded to perform postload track mode boresight missile test. No video appeared in aircraft multi purpose color display. The missile was loaded on a separate tested aircraft with same results, no video.

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 14887

(Continued)

ACTION TAKEN:

15OCT01: NAWC Pt. Mugu requested that MALS-13 Weapons Department place missile in Condition Code "F" and ship to NWS Fallbrook, CA for repair. This is closing action.

ACTION	:	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
SUMMARY		NAWC PT MUGU/311000E	REVIEW DEFICIENCY	COMPLETE	15OCT01

REFERENCES	:	IDENTIFICATION	REFERENCE BRIEF
		VMA-214 MESSAGE 110900ZOCT01	PROBLEM REPORT
		NAWC PT MUGU/311000E MESSAGE	REPLY/CLOSING
		150229ZOCT01	

ACTION	:	VMA-214	CDR	M09436-01-0035	26SEP01	CLOSED
---------------	----------	----------------	------------	-----------------------	----------------	---------------

END ITEM	:	PART/DOC. NO.	FSC	NIIN	NALC
		S/N: 6100046			
FAILED PART:		3647135-100	1410	01-253-8073	PD63
		NOMEN: GUIDED MISSILE, MAVERICK			

DESCRIPTION:

26JUL01: VMA-214 reported during loading evolution of the missile on station 5 of aircraft, ground crew started performing track mode boresight procedures. During the test the ground crew reached step 16 of table three, but no video appeared. Missile was then down loaded and another missile was loaded on the same station and all checks were good. Weapon turned into MALS-13 ordnance awaiting disposition instructions.

ACTION TAKEN:

01OCT01: NAWC Pt. Mugu entered this problem for tracking purposes only. Request MALS-13 Weapons Department place missile in Condition Code "F" and ship to NWS Fallbrook, CA for repair. This is closing action.

ACTION	:	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
SUMMARY		NAWC PT MUGU/311000E	REVIEW DEFICIENCY	COMPLETE	01OCT01

REFERENCES	:	IDENTIFICATION	REFERENCE BRIEF
		VMA-214 MESSAGE 260900ZSEP01	PROBLEM REPORT
		NAWC PT MUGU/311000E MESSAGE	REPLY/CLOSING
		010529ZOCT01	

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 14887 (Continued)

ACTION : VMA-513 CODR M09231-01-0028 25SEP01 CLOSED

	PART/DOC. NO.	FSC	NIIN	NALC
END ITEM :	S/N: 6100552			
FAILED PART:	3647135-100	1410	01-253-8073	PD63
	NOMEN: GUIDED MISSILE, MAVERICK			

DESCRIPTION:

25SEP01: VMA-513 reported missile had no video. The video was extremely washed out. There were no recognizable features. The original launcher and interface wafer were replaced and testing procedures duplicated. The test results were the same; no video. Weapon is being held at for disposition instructions.

ACTION TAKEN:

26SEP01: NAWC Pt. Mugu requested MALS-13 place missile in condition code "F" and ship to NWS Fallbrook, CA for repair. This is closing action.

ACTION :	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
SUMMARY	NAWC PT MUGU/311000E	REVIEW DEFICIENCY		COMPLETE 26SEP01

REFERENCES :	IDENTIFICATION	REFERENCE BRIEF
	VMA-513 MESSAGE 250939ZSEP01	PROBLEM REPORT
	NAWC PT MUGU/311000E MESSAGE	REPLY/CLOSING
	260929ZSEP01	

ACTION : VMA-231 CODR M52948-01-0035 05SEP01 CLOSED

	PART/DOC. NO.	FSC	NIIN	NALC
END ITEM :	3647135-100	1410	01-253-8073	PD63
	NOMEN: GUIDED MISSILE, MAVERICK			
	S/N: 6700233			
FAILED PART:	3647135-100	1410	01-253-8073	PD63
	NOMEN: GUIDED MISSILE, MAVERICK			
	S/N: 6700233			

DESCRIPTION:

26AUG01: It was reported that missile had no video. Missile was loaded on a different aircraft with the same results.

ACTION TAKEN:

06SEP01: NAWC Pt. Mugu requested that missile be placed in condition code "F" and ship to NWS Fallbrook for repair. This is closing action.

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 14887

(Continued)

ACTION : **ACTIVITY/CODE** **ASSIGNMENT** **DUE DATE STATUS**
SUMMARY NAWC PT MUGU/311000E REVIEW DEFICIENCY COMPLETE 06SEP01

REFERENCES : **IDENTIFICATION** **REFERENCE BRIEF**
VMA-231 MESSAGE 051519ZSEP01 PROBLEM REPORT
NAWC PT MUGU/311000E MESSAGE REPLY/CLOSING
061429ZSEP01

ACTION : **VFA-27** **CDR** **R65185-01-0008** **24AUG01 CLOSED**

END ITEM : **PART/DOC. NO.** **FSC** **NIIN** **NALC**
S/N: 6101053
FAILED PART: 3647136-100 6920 01-254-7577 PY15
NOMEN: GUIDED MISSILE, MAVERICK

DESCRIPTION:

26JUL01: VFA-27 reported missile had no video. While in flight pilot was unable to get video display from CATM. CATM and aircraft were tested in accordance with weapons loading manual. CATM was tested on second aircraft with same results.

ACTION TAKEN:

24AUG01: NAWC Pt. Mugu requested NAS Atsugi weapons department place missile in condition code "F", and ship to NWS Fallbrook, CA for repair. This is closing action.

ACTION : **ACTIVITY/CODE** **ASSIGNMENT** **DUE DATE STATUS**
SUMMARY NAWC PT MUGU/311000E REVIEW DEFICIENCY COMPLETE 24AUG01

REFERENCES : **IDENTIFICATION** **REFERENCE BRIEF**
NAWC PT MUGU/311000E MESSAGE REPLY/CLOSING
240629ZAUG01
VFA-27 MESSAGE 240112ZAUG01 PROBLEM REPORT

ACTION : **VMFA-323** **CDR** **M09235-01-0028** **02AUG01 CLOSED**

END ITEM : **PART/DOC. NO.** **FSC** **NIIN** **NALC**
S/N: 6100914
FAILED PART: 3647135-100 1410 01-253-8073 PD63
NOMEN: GUIDED MISSILE, MAVERICK

DESCRIPTION:

30JUL01: VMFA-323 reported missile had no video signal and would not track. Missile was loaded on two additional aircraft with the same result. Turned into CV64 weapons department awaiting disposition instructions.

**MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM**

PROBLEM NO: 14887

(Continued)

ACTION TAKEN:

06AUG01: NAWC Pt. Mugu requested that missile be placed in condition code "F" and shipped to NWS, Fallbrook CA for repair. This is closing action.

ACTION SUMMARY	:	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
		NAWC PT MUGU/311000E	REVIEW DEFICIENCY	COMPLETE	06AUG01

REFERENCES	:	IDENTIFICATION	REFERENCE BRIEF
		VMFA-323 MESSAGE 022100ZAUG01	PROBLEM REPORT
		NAWC PT MUGU/311000E MESSAGE	REPLY/CLOSING
		060129ZAUG01	

ACTION	:	VMA-513	CDR	M09231-01-0017	08JUN01	CLOSED
---------------	----------	----------------	------------	-----------------------	----------------	---------------

END ITEM	:	PART/DOC. NO.	FSC	NIIN	NALC
		S/N: 6700391			
FAILED PART:		3647135-100	1410	01-253-8073	PD63
		NOMEN: GUIDED MISSILE, MAVERICK			

DESCRIPTION:

08JUN01: VMA-513 reported that during weapons load test missile failed steps six and 16. There was no infrared video. The test procedures were repeated with the same results.

ACTION TAKEN:

19JUN01: NAWC Pt. Mugu requested that missile be placed in condition code "F" and shipped to NWS Fallbrook, CA for repair. This is closing action.

ACTION SUMMARY	:	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
		NAWC PT MUGU/311000E	REVIEW DEFICIENCY	COMPLETE	19JUN01

REFERENCES	:	IDENTIFICATION	REFERENCE BRIEF
		VMA-513 MESSAGE 081727ZJUN01	PROBLEM REPORT
		NAWC PT MUGU/311000E MESSAGE	REPLY/CLOSING
		190029ZJUN01	

ACTION	:	VP-1	CDR	R09618-01-0024	04JUN01	CLOSED
---------------	----------	-------------	------------	-----------------------	----------------	---------------

END ITEM	:	PART/DOC. NO.	FSC	NIIN	NALC
		S/N: 6100404			
FAILED PART:		3647136-100	6920	01-254-7577	PY15
		NOMEN: GUIDED MISSILE, MAVERICK			

**MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM**

PROBLEM NO: 14887

(Continued)

DESCRIPTION:

01JUN01: VP-1 reported missile had no infrared cooling. Missile would not cool or activate on any other station. Problem is suspected to be internal equipment degradation in the CATM.

ACTION TAKEN:

07JUN01: NAWC Pt. Mugu requested that missile be placed in condition code "F" and shipped to NWS Fallbrook, CA for repair. This is closing action.

ACTION SUMMARY	: ACTIVITY/CODE NAWC PT MUGU/311000E	ASSIGNMENT REVIEW DEFICIENCY	DUE DATE STATUS COMPLETE 07JUN01
-----------------------	--	--	--

REFERENCES	: IDENTIFICATION VP-1 MESSAGE 041600ZJUN01 NAWC PT MUGU/311000E MESSAGE 070129ZJUN01	REFERENCE BRIEF PROBLEM REPORT REPLY/CLOSING
-------------------	--	---

ACTION	: VFA-27	CODR	R65185-01-0003	15MAY01	CLOSED	
	END ITEM	: PART/DOC. NO.	S/N: 6700548	FSC	NIIN	NALC
	FAILED PART:	3647136-100	6920	01-254-7577	PY15	
		NOMEN:	GUIDED MISSILE, MAVERICK			

DESCRIPTION:

10MAY01: VFA-27 reported missile had no video. Weapon was turned into USS Kitty Hawk weapons department awaiting disposition.

ACTION TAKEN:

17MAY01: NAWC Pt. Mugu requested that the missile be placed in condition code "F" and shipped to NWS Fallbrook, CA for repair. This is closing action.

26OCT01: NAWMU-1 reported that the missile was tested with the TTU-519/E test set and there were no discrepancies found.

ACTION SUMMARY	: ACTIVITY/CODE NAWC PT MUGU/311000E	ASSIGNMENT REVIEW DEFICIENCY	DUE DATE STATUS COMPLETE 17MAY01
-----------------------	--	--	--

REFERENCES	: IDENTIFICATION VFA-27 MESSAGE 151200ZMAY01 NAWC PT MUGU/311000E MESSAGE 170229ZMAY01 NAWMU-1 MESSAGE 260229ZOCT01 NAWC PT MUGU/311000E MESSAGE 300529ZOCT01	REFERENCE BRIEF PROBLEM REPORT REPLY/CLOSING DISPOSITION OF MSL INFO RESPONSE
-------------------	--	--

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 14887 (Continued)

ACTION : VFA-137 CODR V55142-01-0020 06MAY01 CLOSED

END ITEM : PART/DOC. NO. FSC NIIN NALC

S/N: 6101325

FAILED PART: 3647135-100 1410 01-253-8073 PD63

NOMEN: GUIDED MISSILE, MAVERICK

DESCRIPTION:

06MAY01: VFA-137 reported missile failed video during pilot turn-up. Missile was turned into USS Constellation Weapons Department awaiting disposition.

ACTION TAKEN:

15MAY01: NAWC Pt. Mugu requested missile be placed in condition code "F" and shipped to Fallbrook, CA. This is closing action.

ACTION : ACTIVITY/CODE ASSIGNMENT DUE DATE STATUS

SUMMARY NAWC PT MUGU/311000E REVIEW DEFICIENCY COMPLETE 15MAY01

REFERENCES : IDENTIFICATION REFERENCE BRIEF

VFA-137 MESSAGE 060203ZMAY01 PROBLEM REPORT

NAWC PT MUGU/311000E MESSAGE REPLY/CLOSING

150129ZMAY01

ACTION : VFA-105 CODR V65183-01-0016 08APR01 CLOSED

END ITEM : PART/DOC. NO. FSC NIIN NALC

S/N: 6101645

FAILED PART: 3647136-100 6920 01-254-7577 PY15

NOMEN: GUIDED MISSILE, MAVERICK

DESCRIPTION:

05APR01: VFA-105 reported that during post-flight brief, the missile was unable to display video. Missile was subsequently uploaded on two other aircraft with the same results. Missile was turned into weapons department of the USS Harry S. Truman awaiting disposition.

ACTION TAKEN:

10APR01: NAWC Pt. Mugu requested that missile be placed in condition code "F" and shipped to NWS Fallbrook, CA for repair. This is closing action.

ACTION : ACTIVITY/CODE ASSIGNMENT DUE DATE STATUS

SUMMARY NAWC PT MUGU/311000E REVIEW DEFICIENCY COMPLETE 10APR01

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 14887 (Continued)

ACTION : VP-26 CODR V09610-01-0007 12MAR01 CLOSED

END ITEM : PART/DOC. NO. FSC NIIN NALC

S/N: 6100637

LOT: N/A

FAILED PART: 3647136-100 6920 01-254-7577 PY15

NOMEN: GUIDED MISSILE, MAVERICK

DESCRIPTION:

09MAR01: Weapon was inspected with no defects noted. Weapon was loaded, missile on aircraft test was completed with no video observed. Missile system BIT was performed, failing the video portion. Missile was downloaded, and subsequently uploaded on two additional aircraft with a ready for issue LAU-117A issued by missile failed video portion of the missile on aircraft test (MOAT).

ACTION TAKEN:

09MAR01: A duplicate of the original deficiency was sent.

19MAR01: NAWC Pt. Mugu requested missile be placed in condition code "F" and shipped to NWS Fallbrook, CA for repair. This is closing action.

ACTION : ACTIVITY/CODE ASSIGNMENT DUE DATE STATUS

SUMMARY NAWC PT MUGU/311000E REVIEW DEFICIENCY COMPLETE 19MAR01

REFERENCES : IDENTIFICATION REFERENCE BRIEF

VP-26 MESSAGE 122129ZMAR01 PROBLEM REPORT

VP-26 MESSAGE 141104ZMAR01 DUPLICATE PROBLEM REPORT

NAWC PT MUGU/311000E MESSAGE REPLY/CLOSING

190529ZMAR01

ACTION : VMA-542 CODR M52847-01-0009 27FEB01 CLOSED

END ITEM : PART/DOC. NO. FSC NIIN NALC

3647136-100 6920 01-254-7577 PY15

NOMEN: GUIDED MISSILE, MAVERICK

S/N: 6101040

FAILED PART: 3647136-100 6920 01-254-7577 PY15

NOMEN: GUIDED MISSILE, MAVERICK

DESCRIPTION:

21FEB01: VMA-542 reported CATM-65F missile was loaded on station three of aircraft. During pilot preflight checks, pilot indicated unresolved store code. Store codes were reconfirmed by team leader. Team leader changed cable. Pilot decided to continue on with mission. Upon return, missile was loaded on a second aircraft after

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 14887

(Continued)

system checks were performed. Pilot indicated no video during flight.

ACTION TAKEN:

27FEB01: NAWC Pt. Mugu requested that missile be shipped to NWS Fallbrook, CA for repair. This is closing action.

27FEB01: VMA-542 requested cancellation of original deficiency due to an incorrect missile serial number was called out.

27FEB01: VMA-542 resubmitted deficiency with correct missile serial number and reported CATM-65F missile was loaded on station three of aircraft. During pilot preflight checks, pilot indicated unresolved store code. Store codes were reconfirmed by team leader. Team leader changed cable. Pilot decided to continue on with mission. Upon return, missile was loaded on a second aircraft after system checks were performed. Pilot indicated no video during flight.

28FEB01: NAWC Pt. Mugu requested that missile be shipped to NWS Fallbrook, CA for repair. This is closing action.

ACTION	:	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
SUMMARY		NAWC PT MUGU/311000E	REVIEW DEFICIENCY		COMPLETE 28FEB01

REFERENCES	:	IDENTIFICATION	REFERENCE BRIEF
		VMA-542 MEESAGE 261630ZFEB01	PROBLEM REPORT
		NAWC PT MUGU/311000E MESSAGE 270229ZFEB01	REPLY/CLOSING
		VMA-542 MESSAGE 270900ZFEB01	PROBLEM REPORT CANCELLATION
		VMA-542 MESSAGE 270930ZFEB01	RESUBMITTED PROBLEM REPORT
		NAWC PT MUGU/311000E MESSAGE 280129ZFEB01	REPLY/CLOSING

ACTION	:	VS-22	CDR	V09287-01-0010	25FEB01	CLOSED	
		END ITEM	:	PART/DOC. NO.	FSC	NIIN	NALC
				3647135-100	1410	01-253-8073	PD63
				NOMEN: GUIDED MISSILE, MAVERICK			
				S/N: 6100821			
		FAILED PART:		3647135-100	1410	01-253-8073	PD63
				NOMEN: GUIDED MISSILE, MAVERICK			

DESCRIPTION:

25FEB01: VS-22 reported that during routine mission of AGM-65F missile that no infrared imagery video was obtained. AGM-65F was downloaded and AWM-92 test set was connected and wire check was performed with good video obtained. Missile was loaded on F/A-18 aircraft and obtained same negative infrared imagery results. Weapon

**MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM**

PROBLEM NO: 14887

(Continued)

was turned into CVN-75 weapons department awaiting disposition instructions.

ACTION TAKEN:

27FEB01: NAWC Pt. Mugu requested that missile be placed in condition code "F" and shipped to NWS Fallbrook, CA for repair. This is closing action.

ACTION :	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
SUMMARY	NAWC PT MUGU/311000E	REVIEW DEFICIENCY	COMPLETE	27FEB01

REFERENCES :	IDENTIFICATION	REFERENCE BRIEF
	VS-22 MESSAGE 251537ZFEB01	PROBLEM REPORT
	NAWC PT MUGU/311000E MESSAGE	REPLY/CLOSING
	270129ZFEB01	

ACTION :	VP-26	CODR	V09610-00-0001	09FEB01	CLOSED
-----------------	--------------	-------------	-----------------------	----------------	---------------

	PART/DOC. NO.	FSC	NIIN	NALC
END ITEM :	3647135-100	1410	01-253-8073	PD63
	NOMEN: GUIDED MISSILE, MAVERICK			
	S/N: 6100952			
FAILED PART:	3647135-100	1410	01-253-8073	PD63
	NOMEN: GUIDED MISSILE, MAVERICK			

DESCRIPTION:

09DEC00: VP-26 reported that after missile was loaded, the load crew commenced with missile on aircraft test. With power applied to aircraft, missile seeker head was fired up. Once missile warmed up and the proper cues were given via the missile armament panel, the following switches were selected: "VDC, PEP, Radar VID, Missile Station, cool and activate". Missile came online approximately four minutes after switch selection. Load team could not obtain proper video from seeker head. The cross hairs were visible but the video was dark across the entire screen with no identifiable picture definition.

ACTION TAKEN:

21FEB01: NAWC Pt. Mugu requested that missile be placed in condition code "F" and shipped to NWS Fallbrook , CA for repair. This is closing action.

ACTION :	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
SUMMARY	NAWC PT MUGU/311000E	REVIEW DISCREPANCY	COMPLETE	21FEB01

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 14887

(Continued)

ACTION TAKEN:

27NOV00: NAWC Pt. Mugu requested that missile be placed in condition code "F" and shipped to NWS Fallbrook, CA for repair. This is closing action.

ACTION	:	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
SUMMARY		NAWC PT MUGU/311000E	REVIEW DEFICIENCY	COMPLETE	27NOV00

REFERENCES	:	IDENTIFICATION	REFERENCE BRIEF
		VMFA-312 MESSAGE 071600ZNOV00	PROBLEM REPORT
		NAWC PT MUGU/311000E MESSAGE	REPLY/CLOSING
		270429ZNOV00	

ACTION	:	VFA-195	CODR	R09706-00-0048	06NOV00	CLOSED
---------------	----------	----------------	-------------	-----------------------	----------------	---------------

END ITEM	:	PART/DOC. NO.	FSC	NIIN	NALC
		S/N: 6101053			
FAILED PART:		3647136-100	6920	01-254-7577	PY15
		NOMEN: GUIDED MISSILE, MAVERICK			

DESCRIPTION:

23OCT00: VFA-195 reported missile had no video. The weapon was turned into USS Kitty Hawk weapons department awaiting disposition.

ACTION TAKEN:

06NOV00: NAWC Pt. Mugu requested that missile be placed in condition code "F" and shipped to NWS Fallbrook, CA for repair. This is closing action.

ACTION	:	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
SUMMARY		NAWC PT MUGU/311000E	REVIEW DEFICIENCY	COMPLETE	06NOV00

REFERENCES	:	IDENTIFICATION	REFERENCE BRIEF
		NAWC PT MUGU/311000E MESSAGE	REPLY/CLOSING
		060529ZNOV00	
		VFA-195 MESSAGE 061100ZNOV00	PROBLEM REPORT

ACTION	:	VFA-83	CODR	V09223-00-0027	24OCT00	CLOSED
---------------	----------	---------------	-------------	-----------------------	----------------	---------------

END ITEM	:	PART/DOC. NO.	FSC	NIIN	NALC
		S/N: 6100244			
FAILED PART:		3647136-100	6920	01-254-7577	PY15
		NOMEN: GUIDED MISSILE, MAVERICK			

**MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM**

PROBLEM NO: 14887

(Continued)

DESCRIPTION:

23OCT00: VFA-83 reported missile lost video during flight. Missile was turned into the USS George Washington weapons department awaiting disposition.

ACTION TAKEN:

06NOV00: NAWC Pt. Mugu requested that the USS George Washington weapons department place missile in condition code "F" and ship to NWS Fallbrook, CA for repair. This is closing action.

ACTION	:	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
SUMMARY		NAWC PT MUGU/311000E	REVIEW DEFICIENCY	COMPLETE	06NOV00

REFERENCES	:	IDENTIFICATION	REFERENCE BRIEF
		VFA-83 MESSAGE 241033ZOCT00	PROBLEM REPORT
		NAWC PT MUGU/311000E MESSAGE	REPLY/CLOSING
		060829ZNOV00	

ACTION	:	VP-45	CODR	V09665-00-0023	06OCT00	CLOSED	
		END ITEM	:	PART/DOC. NO.	FSC	NIIN	NALC
				S/N: 6700230			
		FAILED PART:		3647135-100	1410	01-253-8073	PD63
				NOMEN: GUIDED MISSILE, MAVERICK			

DESCRIPTION:

28SEP00: VP-45 reported missile failed operation checks with no video. A new missile was loaded on station 11 with no further discrepancies noted. Missile was turned into NAS Sigonella station weapons department awaiting disposition.

ACTION TAKEN:

11OCT00: NAWC Pt. Mugu requested that NAS Sigonella weapons department place missile in condition code "F" and ship to NWS Fallbrook, CA for repair. This is closing action.

ACTION	:	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
SUMMARY		NAWC PT MUGU/311000E	REVIEW DEFICIENCY	COMPLETE	11OCT00

REFERENCES	:	IDENTIFICATION	REFERENCE BRIEF
		VP-45 MESSAGE 061200ZOCT00	PROBLEM REPORT
		NAWC PT MUGU/311000E MESSAGE	REPLY/CLOSING
		110129ZOCT00	

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 14887 (Continued)

ACTION : VP-45 CODR V09665-00-0024 06OCT00 CLOSED

END ITEM : PART/DOC. NO. FSC NIIN NALC

S/N: 6700556

FAILED PART: 3647135-100 1410 01-253-8073 PD63

NOMEN: GUIDED MISSILE, MAVERICK

DESCRIPTION:

27SEP00: VP-45 reported that missile failed operations check with no video output. The missile was downloaded. Aircraft weapon station was tested, no discrepancies noted. Missile was turned into NAS Sigonella station weapons department awaiting disposition.

ACTION TAKEN:

11OCT00: NAWC Pt. Mugu requested that the missile be shipped to NWS Fallbrook, CA for repair. This is closing action.

ACTION : ACTIVITY/CODE ASSIGNMENT DUE DATE STATUS

SUMMARY NAWC PT MUGU/311000E REVIEW DEFICIENCY COMPLETE 11OCT00

REFERENCES : IDENTIFICATION REFERENCE BRIEF

VP-45 MESSAGE 061205ZOCT00 PROBLEM REPORT

NAWC PT MUGU/311000E MESSAGE REPLY/CLOSING

110229ZOCT00

ACTION : VP-45 CODR V09665-00-0017 21SEP00 CLOSED

END ITEM : PART/DOC. NO. FSC NIIN NALC

S/N: 6700454

FAILED PART: 3647135-100 1410 01-253-8073 PD63

NOMEN: GUIDED MISSILE, MAVERICK

DESCRIPTION:

19SEP00: VP-45 reported that missile had no video present during post-load. The seeker head would slew with the cursor, but had no video. Missile was turned into NAS Sigonella station awaiting disposition instructions.

ACTION TAKEN:

26SEP00: NAWC Pt. Mugu requested that NAS Sigonella weapons department place missile in condition code "F" and ship to NWS Fallbrook, CA. This is closing action.

ACTION : ACTIVITY/CODE ASSIGNMENT DUE DATE STATUS

SUMMARY NAWC PT MUGU/311000E REVIEW DEFICIENCY COMPLETE 26SEP00

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 14887

(Continued) |

REFERENCES : IDENTIFICATION

VP-45 MESSAGE 211200ZSEP00
NAWC PT MUGU/311000E MESSAGE
260029ZSEP00

REFERENCE BRIEF

PROBLEM REPORT
REPLY/CLOSING

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 14892 CLOSED

END ITEM	NOMENCLATURE	PART/DOC. NO.	FSC	NIIN	NALC
:	GUIDED MISSILE, MAVERICK	3384305-101	6920	01-238-0123	3W70
	GUIDED MISSILE, MAVERICK	3647135-100	1410	01-253-8073	PD63
	GUIDED MISSILE, MAVERICK	3647136-100	6920	01-254-7577	PY15

EI CNTRL NO:

PROB BRIEF : MISSILE FAILED TO IDENT ON AIRCRAFT

PROBLEM : AGM-65F missile would not IDENT on aircraft.
DESCRIPTION

PREVENTIVE : There is no preventive action.
ACTION

CORRECTIVE : No corrective action has yet been established as specific causative
ACTION factors have not been identified.

OCCURRENCES:	SOURCE	TYPE	DOCUMENT NO.	DATE	DR STATUS
	VP-45	CODR	V09665-00-0018	26SEP00	CLOSED
	VMFA(AW)-121	CODR	M09257-00-0009	08MAY00	CLOSED
	VFA-87	CODR	V63922-99-0038	28AUG99	CLOSED *
	VFA-87	CODR	V63922-99-0032	15AUG99	CLOSED *
	VFA-87	CODR	V63922-99-0026	10AUG99	CLOSED *
	VFA-87	CODR	V63922-99-0024	23JUL99	CLOSED *
	VMFA-251	CODR	M09241-96-0021	11DEC96	CLOSED *
	NWS YORKTOWN	PQDR II	N00109-94-3123	18AUG94	CLOSED *
	VFA-136	EMR	V55141-91-0053	05NOV91	CLOSED *

* ACTION REPORTED IN PREVIOUS PUBLICATION

ACTION : VP-45 CODR V09665-00-0018 26SEP00 CLOSED

END ITEM	PART/DOC. NO.	FSC	NIIN	NALC
:	S/N: 6100858			
FAILED PART:	3647135-100	1410	01-253-8073	PD63
NOMEN:	GUIDED MISSILE, MAVERICK			

DESCRIPTION:

24SEP00: VP-45 reported missile flew with aircraft on a nine hour mission with 23 minutes of total active time. No discrepancies observed. After turnaround of aircraft for second mission of the day, and upon missile power up, the station 11 three phase 115VAC circuit breaker tripped and would not reset. The missile was downloaded and is being held at NAS Sigonella weapons department awaiting disposition.

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 14892

(Continued)

ACTION TAKEN:

02OCT00: NAWC Pt. Mugu requested NAS Sigonella weapons department place missile in condition code "F" and ship to NWS Fallbrook, CA for repair. This is closing action.

ACTION	:	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
SUMMARY		NAWC PT MUGU/311000E	REVIEW DEFICIENCY	COMPLETE	02OCT00

REFERENCES	:	IDENTIFICATION	REFERENCE BRIEF
		VP-45 MESSAGE 261200ZSEP00	PROBLEM REPORT
		NAWC PT MUGU/311000E MESSAGE	REPLY/CLOSING
		020329ZOCT00	

ACTION	:	VMFA(AW)-121	CODR	M09257-00-0009	08MAY00	CLOSED
---------------	----------	---------------------	-------------	-----------------------	----------------	---------------

END ITEM	:	PART/DOC. NO.	FSC	NIIN	NALC
		S/N: 5101284			
FAILED PART:		3384304-101	1410	01-158-2872	PB69
		NOMEN: GUIDED MISSILE, MAVERICK			

DESCRIPTION:

22MAR00: Squadron reports aircraft checked and loaded in accordance with the weapons loading manuals. During pre-flight check weapon fail displayed. Aircraft was downloaded and rechecked. The LAU-117 Launcher was checked by the Intermediate maintenance activity. Both checks were completed without discrepancies. Another weapon was loaded on the the aircraft with no problems noted.

ACTION TAKEN:

09MAY00: NAWC Pt. Mugu has reviewed the reported deficiency and requests VMFA(AW)-121 place the subject weapon in condition code "F" and return the weapon for repair to NWS Fallbrook, CA. It is further requested that NWS Fallbrook provide a copy of missile test data to ALCON.

15MAR01: NAWC Pt. Mugu verified, via AWARS, that testing was completed at NWS Fallbrook and missile was placed in Condition Code "A". This is closing action.

ACTION	:	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
SUMMARY		NAWC PT MUGU/311000E	REVIEW DEFICIENCY	COMPLETE	09MAY00

REFERENCES	:	IDENTIFICATION	REFERENCE BRIEF
		VMFA(AW)-121 MESSAGE 080402ZMAY00	PROBLEM REPORT
		NAWC PT MUGU/311000E MESSAGE	INTERIM RESPONSE
		090029ZMAY00	
		NAWC PT MUGU/311000E AWARS 15MAR01	TEST DATA VERIFIED

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 14893 CLOSED

	NOMENCLATURE	PART/DOC. NO.	FSC	NIIN	NALC
END ITEM :	GUIDED MISSILE, MAVERICK	3647135-100	1410	01-253-8073	PD63
	GUIDED MISSILE, MAVERICK	3647136-100	6920	01-254-7577	PY15

EI CNTRL NO:

PROB BRIEF : MISSILE FAILED TO CAGE

PROBLEM : Upon return from flight aircrews reported missile would not
DESCRIPTION cage/uncage.

PREVENTIVE : There is no preventive action.
ACTION

CORRECTIVE : No corrective action has yet been established as specific causative
ACTION factors have not been identified.

	SOURCE	TYPE	DOCUMENT NO.	DATE	DR STATUS
OCCURRENCES:	VFA-97	CODR	R63923-01-0015	21MAY01	CLOSED
	VMFA(AW)-224	CODR	M09439-00-0020	15AUG00	CLOSED *
	VMFA(AW)-224	CODR	M09439-96-0029	19AUG96	CLOSED *
	VA-36	EMR	V09941-92-0074	04NOV92	CLOSED *
	VFA-131	EMR	R63934-91-0045	02NOV91	CLOSED *

* ACTION REPORTED IN PREVIOUS PUBLICATION

ACTION : VFA-97 CODR R63923-01-0015 21MAY01 CLOSED

	PART/DOC. NO.	FSC	NIIN	NALC
END ITEM :				
	S/N: 5101305			
FAILED PART:	3384305-100	6290	01-254-7577	3W70
	NOMEN: GUIDED MISSILE, TRAINING			

DESCRIPTION:

15MAY01: VFA-97 reported missile failed to cage. Weapon was turned into NAS Lemoore Weapons Department awaiting disposition.

ACTION TAKEN:

29MAY01: NAWC Pt. Mugu requested NAS Lemoore weapons department to place missile in condition code "F" and ship to NWS Fallbrook, CA for repair. This is closing action.

	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
ACTION SUMMARY :	NAWC PT MUGU/311000E	REVIEW DEFICIENCY		COMPLETE 29MAY01

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 14893

(Continued) |

REFERENCES : IDENTIFICATION

VFA-97 MESSAGE 211600ZMAY01
NAWC PT MUGU/311000E MESSAGE
290029ZMAY01

REFERENCE BRIEF

PROBLEM REPORT
REPLY/CLOSING

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 14981 CLOSED

	NOMENCLATURE	PART/DOC. NO.	FSC	NIIN	NALC
END ITEM :	GUIDED MISSILE, MAVERICK	3647135-100	1410	01-253-8073	PD63
	GUIDED MISSILE, MAVERICK	3647136-100	6920	01-254-7577	PY15

EI CNTRL NO:

PROB BRIEF : SAFE AND ARM MECHANISM SUSPECTED OUT OF ALIGNMENT

PROBLEM : Unable to insert T-handle in Safe and Arm device. Suspect that the
DESCRIPTION Safe and Arm device securing screws were loose.

PREVENTIVE : There is no preventive action.
ACTION

CORRECTIVE : Problem will continue to be monitored for processing of the mishap
ACTION weapons in order to identify specific causative factors. Once the nature of the deficiency is known, preventive and corrective action will be established.

	SOURCE	TYPE	DOCUMENT NO.	DATE	DR STATUS
OCCURRENCES:	VMFA-312	CODR	M09253-01-0009	03APR01	CLOSED
	VA-196	CODR	R09093-96-0014	02SEP96	CLOSED *
	VA-75	CODR	V09628-95-0009	19DEC95	CLOSED *
	MALS-13	CODR	M57082-95-0067	06SEP95	CLOSED *
	VFA-113	CODR	R09092-94-0051	04MAY94	CLOSED *
	VFA-131	EMR	R63934-94-0004	24FEB94	CLOSED *
	CARAIRWING-7	EMR	V09736-92-0001	07FEB92	CLOSED *

* ACTION REPORTED IN PREVIOUS PUBLICATION

ACTION : VMFA-312 CODR M09253-01-0009 03APR01 CLOSED

	PART/DOC. NO.	FSC	NIIN	NALC
END ITEM :				
	S/N: 6100846			
FAILED PART:	3647136-100	6920	01-254-7577	PY15
	NOMEN: GUIDED MISSILE, MAVERICK			

DESCRIPTION:

30MAR01: VMFA-312 reported missile de-arm crew had considerable difficulty installing safe/arm key into missile safe/arm mechanism. The de-arm crew team leader inspected missile and discovered the slot ring on the safe/arm mechanism had turned 180 degrees causing the safe/arm key to improperly align.

ACTION TAKEN:

06APR01: NAWC Pt. Mugu requested USS Truman weapons department place missile in condition code "F" and ship to Naval Weapons Station Fallbrook for repair and test. This is closing action.

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 14981

(Continued)

ACTION	:	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
SUMMARY	:	NAWC PT MUGU/311000E	REVIEW DEFICIENCY		COMPLETE 06APR01

REFERENCES	:	IDENTIFICATION	REFERENCE BRIEF
	:	VMFA-312 MESSAGE 031312ZAPR01	PROBLEM REPORT
	:	NAWC PT MUGU/311000E MESSAGE	REPLY/CLOSING
	:	060129ZAPR01	

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 15044 CLOSED

END ITEM	NOMENCLATURE	PART/DOC. NO.	FSC	NIIN	NALC
:	GUIDED MISSILE, MAVERICK	3384304-101	1410	01-158-2872	PB69
	GUIDED MISSILE, MAVERICK	3647135-100	1410	01-253-8073	PD63
	GUIDED MISSILE, MAVERICK	3647136-100	6920	01-254-7577	PY15
	MISSILE GUIDED, INTERCEPT	3819500-130	1410	01-375-0439	PU46

EI CNTRL NO: 01-0014

PROB BRIEF : FAILURE TO SLEW PROPERLY

PROBLEM : Weapon's Seeker failed to slew upon command.
DESCRIPTION

PREVENTIVE : There is no preventive action.
ACTION

CORRECTIVE : No corrective action is contemplated at this time. However, problem
ACTION will continue to be monitored for the processing of this weapon until testing has been performed and specific causative factors are known.

OCCURRENCES:	SOURCE	TYPE	DOCUMENT NO.	DATE	DR STATUS
	VFA-94	CODR	R09295-01-0018	29MAY01	CLOSED
	VMFA-323	CODR	M09235-00-0022	19JUN00	CLOSED
	VFA-147	CODR	R63925-99-0018	23AUG99	CLOSED *
	VFA-192	CODR	R09076-99-0016	13APR99	CLOSED *
	VFA-192	CODR	R09076-99-0017	13APR99	CLOSED *
	VS-22	CODR	V09287-96-0039	20DEC96	CLOSED *
	VFA-195	CODR	R09706-96-0061	08NOV96	CLOSED *
	VFA-82	CODR	V09122-96-0041	25JUL96	CLOSED *
	VFA-82	CODR	V09122-96-0039	17JUL96	CLOSED *
	VA-75	CODR	V09628-96-0105	12JUL96	CLOSED *
	VS-22	CODR	V09287-96-0015	20JUN96	CLOSED *
	VA-75	CODR	V09628-96-0103	21MAR96	CLOSED *
	VFA-192	CODR	R09076-95-0007	04OCT95	CLOSED *
	VFA-105	CODR	V65183-94-0033	26NOV94	CLOSED *
	NOC FALLBROOK	PQDR II	N00396-94-0121	18OCT94	CLOSED *
	VA-196	CODR	R09093-94-0046	17JUN94	CLOSED *
	VP-26	CODR	V09610-94-0004	15FEB94	CLOSED *
	VA-52	CODR/EIR	R09283-94-0008	07FEB94	CLOSED *
	VFA-192	CODR	R09076-94-0001	05JAN94	CLOSED *
	VA-52	CODR	R09283-93-0048	24SEP93	CLOSED *
	VA-65	EMR	V09710-92-0040	10APR92	CLOSED *

* ACTION REPORTED IN PREVIOUS PUBLICATION

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 15044 (Continued)

ACTION : VFA-94 CODR R09295-01-0018 29MAY01 CLOSED

END ITEM : PART/DOC. NO. FSC NIIN NALC

S/N: 6101138

FAILED PART: 3647136-100 6920 01-254-7577 PY15

NOMEN: GUIDED MISSILE, MAVERICK

DESCRIPTION:

24MAY01: VFA-94 reported missile would not slew during flight. Infrared seeker head remained locked in the down and left position. Missile was loaded on different aircraft and power up bit was performed. Missile seeker head would not cage or slew.

ACTION TAKEN:

30MAY01: NAWC Pt. Mugu requested missile be placed in condition code "F" and shipped to NWS Fallbrook, CA for repair. This is closing action.

ACTION : ACTIVITY/CODE ASSIGNMENT DUE DATE STATUS

SUMMARY NAWC PT MUGU/311000E REVIEW DEFICIENCY COMPLETE 30MAY01

REFERENCES : IDENTIFICATION REFERENCE BRIEF

VFA-94 MESSAGE 290940ZMAY01 PROBLEM REPORT

NAWC PT MUGU/311000E MESSAGE REPLY/CLOSING

300329ZMAY01

ACTION : VMFA-323 CODR M09235-00-0022 19JUN00 CLOSED

END ITEM : PART/DOC. NO. FSC NIIN NALC

3384304-101 1410 01-158-2872 PB69

NOMEN: GUIDED MISSILE, MAVERICK

S/N: 5000549

FAILED PART: 3384304-101 1410 01-158-2872 PB69

NOMEN: GUIDED MISSILE, MAVERICK

DESCRIPTION:

08JUN00: VMFA 323 reported loading crew applied external power to missile in accordance with referenced manual. After Maverick timer counted down, cage/uncage switch was pressed and released. An "X" on Maverick display swept left and right. Further attempts to slew were unsuccessful.

ACTION TAKEN:

12FEB01: NAWC Pt. Mugu requested VMFA-323 weapons department place missile in condition code "F" and ship to NWS Fallbrook, CA for repair. This is closing action.

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 15044

(Continued)

ACTION	:	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
SUMMARY	:	NAWC PT MUGU/311000E	REVIEW DEFICIENCY		COMPLETE 14FEB01
REFERENCES	:	IDENTIFICATION		REFERENCE BRIEF	
	:	VMFA-323 MESSAGE 190700ZJUN00		PROBLEM REPORT	
	:	NAWC PT MUGU/311000E MESSAGE		REPLY/CLOSING	
	:	120129ZFEB01			

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 15436 CLOSED

END ITEM	NOMENCLATURE	PART/DOC. NO.	FSC	NIIN	NALC
:	GUIDED MISSILE, MAVERICK	3384304-101	1410	01-158-2872	PB69
	GUIDED MISSILE, MAVERICK	3384305-101	6920	01-238-0123	3W70
	GUIDED MISSILE, MAVERICK	3647135-100	1410	01-253-8073	PD63
	GUIDED MISSILE, MAVERICK	3647136-100	6920	01-254-7577	PY15

EI CNTRL NO:

PROB BRIEF : MISSILE FAILED TO LOCK ON TARGET LOADED ON AIRCRAFT

PROBLEM DESCRIPTION : This Problem addresses incidents in which CATM-65F missiles failed on aircraft, as determined by BIT or pilot perceived performance degradation (excluding video/cooling failures which are documented in AWCAP Problem 14887).

PREVENTIVE ACTION : There is no preventive action.

CORRECTIVE ACTION : No corrective action can be prescribed until causative factors are known.

OCCURRENCES:	SOURCE	TYPE	DOCUMENT NO.	DATE	DR STATUS
	VFA-15	CODR	V09015-01-0040	24JUL01	CLOSED
	VFA-15	CODR	V09015-99-0077	25AUG99	CLOSED *
	HMM-265	CODR	M09404-96-0012	17APR96	CLOSED *
	NWS YORKTOWN	PQDR II	N00109-95-3079	01AUG95	CLOSED *
	NSWC FALLON	CODR	N68847-95-0016	21MAR95	CLOSED *
	VFA-136	CODR	V55141-94-0803	28MAR94	CLOSED *
	VA-75	CODR/EIR	V09628-94-0005	15MAR94	CLOSED *
	VA-85	CODR	V09225-94-0006	11MAR94	CLOSED *
	VA-52	CODR	R09283-93-0033	07JUL93	CLOSED *
	VFA-81	EMR	V09221-93-0009	13APR93	CLOSED *

* ACTION REPORTED IN PREVIOUS PUBLICATION

ACTION : VFA-15 CODR V09015-01-0040 24JUL01 CLOSED

END ITEM	PART/DOC. NO.	FSC	NIIN	NALC
:	S/N: 5000598			
FAILED PART:	3384304-101	1410	01-158-2872	PB69
NOMEN:	GUIDED MISSILE, MAVERICK			

DESCRIPTION: 15JUL01: VFA-15 pilot reported missile would not track during flight.

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 15436

(Continued)

ACTION TAKEN:

26JUL01: NAWC Pt. Mugu requested that the weapons department place missile in condition code "F" and ship to NWS Fallbrook, CA for repair. This is closing action.

ACTION	:	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
SUMMARY		NAWC PT MUGU/311000E	REVIEW DEFICIENCY	COMPLETE	26JUL01

REFERENCES	:	IDENTIFICATION	REFERENCE BRIEF
		VFA-15 MESSAGE 240905ZJUL01	PROBLEM REPORT
		NAWC PT MUGU/311000E MESSAGE	REPLY/CLOSING
		260029ZJUL01	

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 15502 CLOSED

END ITEM	NOMENCLATURE	PART/DOC. NO.	FSC	NIIN	NALC
:	GUIDED MISSILE, MAVERICK	3384304-101	1410	01-158-2872	PB69
	GUIDED MISSILE, MAVERICK	3647135-100	1410	01-253-8073	PD63

EI CNTRL NO: 93-0002

PROB BRIEF : MISSILE FAILED TO FIRE

PROBLEM : This problem addresses incidents in which an AGM-65F missile failed
DESCRIPTION to fire although preflight checks were performed with no discrepancies noted and all cockpit indications were normal.

PREVENTIVE : There is no preventive action.
ACTION

CORRECTIVE : No corrective action can be prescribed until causative factors are
ACTION known.

OCCURRENCES:	SOURCE	TYPE	DOCUMENT NO.	DATE	DR STATUS
	VMFA-232	CODR	M09242-01-0007	28FEB01	CANCELED
	VP-8	CODR	V09661-00-0008	27MAR00	CLOSED
	VFA-87	CODR	V63922-99-0023	03AUG99	CLOSED *
	VFA-34	CODR	V09070-99-0009	21JUL99	CLOSED *
	VFA-15	CODR	V09015-99-0060	14JUL99	CLOSED *
	VMA-223	CODR	M09438-99-0022	12JUL99	CLOSED *
	VFA-15	CODR	V09015-99-0039	29MAY99	CLOSED *
	NSAWC FALLON	CODR	N69190-99-0046	24MAY99	CLOSED *
	MAWTS-1	CODR	M55167-99-0002	09APR99	CLOSED *
	VFA-192	CODR	R09076-98-0049	06NOV98	CLOSED *
	VMA-223	CODR	M09438-98-0023	22SEP98	CLOSED *
	VFA-87	CODR	V63922-98-0020	04AUG98	CLOSED *
	VFA-115	CODR	R09604-97-0025	26AUG97	CLOSED *
	VFA-15	CODR	V09015-96-0046	16OCT96	CLOSED *
	VMFA-312	CODR	M09253-96-0014	07JUN96	CLOSED *
	VFA-94	CODR	R09295-95-0043	22NOV95	CLOSED *
	VMA-231	CODR	M52948-95-0021	10SEP95	CLOSED *
	VMA-231	CODR	M52948-94-0030	29JUL94	CLOSED *
	VFA-192	CODR	R09076-93-0018	17JUN93	CLOSED *

* ACTION REPORTED IN PREVIOUS PUBLICATION

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 15502 (Continued)

ACTION : VMFA-232 CODR M09242-01-0007 28FEB01 CANCELED

END ITEM : PART/DOC. NO. FSC NIIN NALC
 3647135-100 1410 01-253-8073 PD63
 NOMEN: GUIDED MISSILE, MAVERICK
 S/N: 6100815

FAILED PART: 3647135-100 1410 01-253-8073 PD63
 NOMEN: GUIDED MISSILE, MAVERICK
 S/N: 6100815

DESCRIPTION:

26FEB01: VMFA-232 reported missile failed to launch, resulting in a hung and lock indication. Pilot returned to base, where upon the missile was saved.

ACTION TAKEN:

05MAR01: NAWC Pt. Mugu requested MALS-11 place missile in condition code "F", and ship to NWS Fallbrook for test and repair. This is closing action.

06MAR01: NAWC Pt. Mugu received email from VMFA-232 stating that the problem was found to be with the aircraft station and not the subject missile.

09MAR01: NAWC Pt. Mugu reported that the problem was found to be with the aircraft station and not subject missile, and requested cancellation of response message to original deficiency received from VMFA-232.

ACTION : ACTIVITY/CODE ASSIGNMENT DUE DATE STATUS

SUMMARY NAWC PT MUGU/311000E REVIEW DEFICIENCY COMPLETE 05MAR01

REFERENCES : IDENTIFICATION REFERENCE BRIEF

VMFA-232 MESSAGE 280203ZFEB01 PROBLEM REPORT

NAWC PT MUGU/311000E MESSAGE REPLY/CLOSING

050929ZMAR01

NAWC PT MUGU/321200E EMAIL 06MAR01 REPORT CLARIFICATION

NAWC PT MUGU/311000E MESSAGE PROBLEM CANCELLATION

090129ZMAR01

ACTION : VP-8 CODR V09661-00-0008 27MAR00 CLOSED

END ITEM : PART/DOC. NO. FSC NIIN NALC
 S/N: 6100220

FAILED PART: 3647135-100 1410 01-253-8073 PD63
 NOMEN: GUIDED MISSILE, MAVERICK

**MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM**

PROBLEM NO: 15502

(Continued)

DESCRIPTION:

24MAR00: Aircraft carrying two live AGM-65F Missiles departed from Naval Air Station Sigonella Sicily, Italy for a missile flight. All system checks (Video and boresighting) were performed successfully. The aircraft arrived on the range and made several practice runs over the target. On the final run the crew selected station 16 on the starboard side of the aircraft. All indications were go. Tacco attempted to launch the first target with negative results. Tacco reported the indications received at the map display were as follows:

Launch command was sent and No launch detected flight station took control and tried to launch the maverick from the co-pilots position with negative results. The aircraft positioned for another run. The tacco deselected station 16, selected station 11 and successfully launched the second missile from the port side of the aircraft. During post flight checks in accordance with applicable manuals. The system operational checks 4.0 on deck. The LAU-117 missile rail was sent to AIMD for test and check. The launcher test was successful with no problems noted.

ACTION TAKEN:

03APR00: NAWC Pt. Mugu request return subject weapon for repair to Weapons Station Fallbrook. Ensure a copy of this message accompanies weapon. Document logbook and records "Intermittant lock and weapon failed to fire". Request Weapons Station Fallbrook provide test results upon processing weapon.

15MAR01: NAWC Pt. Mugu verified, via AWARS, that testing was completed at NWS Fallbrook and missile was placed in condition code "A". This is closing action.

ACTION	:	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
SUMMARY		NAWC PT MUGU/311000E	REVIEW DEFICIENCY		COMPLETE 03APR00

REFERENCES	:	IDENTIFICATION	REFERENCE BRIEF
		VP-8 MESSAGE 271731ZMAR00	PROBLEM REPORT
		NAWC PT MUGU/311000E MESSAGE 030629ZAPR00	INTERIM RESPONSE
		NAWC PT MUGU/311000E AWARS 15MAR01	TEST DATA VERIFIED

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 15594 OPEN

END ITEM : NOMENCLATURE PART/DOC. NO. FSC NIIN NALC
GUIDED MISSILE, MAVERICK 3647135-100 1410 01-253-8073 PD63

EI CNTRL NO:

PROB BRIEF : MISSILE FAILED TO FUNCTION PROPERLY WHEN LAUNCHED

PROBLEM : This problem addresses incidents in which missiles were observed to
DESCRIPTION have functioned improperly upon launch.

PREVENTIVE : No preventive action is recommended as the specific cause of the
ACTION malfunctions could not be determined.

CORRECTIVE : There is no corrective action.
ACTION

OCCURRENCES:	SOURCE	TYPE	DOCUMENT NO.	DATE	DR STATUS
	VP-10	CODR	V09639-01-0015	04OCT01	OPEN
	VP-26	CODR	V09610-01-0009	21APR01	CLOSED
	VFA-94	CODR	R09295-01-0005	19FEB01	CLOSED
	VS-32	CODR	V09353-99-0017	24OCT99	CLOSED *
	VA-52	CODR	R09283-93-0067	22DEC93	CLOSED *

* ACTION REPORTED IN PREVIOUS PUBLICATION

ACTION : VP-10 CODR V09639-01-0015 04OCT01 OPEN

END ITEM :	PART/DOC. NO.	FSC	NIIN	NALC
	S/N: 6101635			
FAILED PART:	3647135-100	1410	01-253-8073	PD63
NOMEN:	GUIDED MISSILE, MAVERICK			

DESCRIPTION:

27SEP01: VP-10 reported flight crew observed missile leaving rail normally then executed a steep dive while rocket motor was still burning. Missile detonated upon water impact. During post flight, release and control checks were completed. LAU-118 turned in for test. No discrepancies noted.

ACTION TAKEN:

05OCT01: NAWC Pt. Mugu reported that this is the third such incident reported regarding this missile flight anomaly. Investigation has been initiated to determine possible causes of this type failure. Results of investigation will be provided by separate correspondence. Deficiency report is to remain open at this time.

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 15594

(Continued)

ACTION	:	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
SUMMARY		NAWC PT MUGU/311000E	INVESTIGATE	03JAN02	OPEN

REFERENCES	:	IDENTIFICATION	REFERENCE BRIEF
		VP-10 MESSAGE 041557ZOCT01	PROBLEM REPORT
		NAWC PT MUGU/311000E MESSAGE	INTERIM RESPONSE
		050729ZOCT01	

ACTION	:	VP-26	CODR	V09610-01-0009	21APR01 CLOSED
---------------	----------	--------------	-------------	-----------------------	-----------------------

		PART/DOC. NO.	FSC	NIIN	NALC
END ITEM	:				
		S/N: 6100911			
FAILED PART:		3647135-100	1410	01-253-8073	PD63
		NOMEN: GUIDED MISSILE, MAVERICK			

DESCRIPTION:

20APR01: VP-26 reported missile left the port wing, flew straight ahead and immediately climbed through aircraft altitude. The missile rolled counterclockwise, nosed over and dove sharply down and to the left.

ACTION TAKEN:

03MAY01: NAWC Pt. Mugu conducted an analysis of the deficiency and firing report and it appears that the missile malfunctioned because of a possible failure to the control section. This is closing action.

ACTION	:	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
SUMMARY		NAWC PT MUGU/311000E	REVIEW DEFICIENCY	COMPLETE	03MAY01

REFERENCES	:	IDENTIFICATION	REFERENCE BRIEF
		VP-26 MESSAGE 211135ZAPR01	PROBLEM REPORT
		NAWC PT MUGU/311000E MESSAGE	REPLY/CLOSING
		030329ZMAY01	

ACTION	:	VFA-94	CODR	R09295-01-0005	19FEB01 CLOSED
---------------	----------	---------------	-------------	-----------------------	-----------------------

		PART/DOC. NO.	FSC	NIIN	NALC
END ITEM	:				
		S/N: 6101690			
FAILED PART:		3647135-100	1410	01-253-8073	PD63
		NOMEN: GUIDED MISSILE, MAVERICK			

DESCRIPTION:

08FEB01: VFA-94 reported that missile failed to perform properly after launch. During missile firing exercise pilot reported firing missile and missile did not guide to target. Missile made a circle, flew straight, made another circle then free fell to the ground.

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 15594

(Continued)

ACTION TAKEN:

21FEB01: NAWC Pt. Mugu has documented this problem has been entered for tracking purposes only. The problem is being tracked for future occurances. This is closing action.

ACTION	:	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
SUMMARY		NAWC PT MUGU/311000E	REVIEW DEFICIENCY	COMPLETE	21FEB01

REFERENCES	:	IDENTIFICATION	REFERENCE BRIEF
		VFA-94 MESSAGE 191530ZFEB01	PROBLEM REPORT
		NAWC PT MUGU/311000E MESSAGE	REPLY/CLOSING
		211029ZFEB01	

**MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM**

PROBLEM NO: 15694 **CLOSED**

END ITEM :	NOMENCLATURE GUIDED MISSILE, MAVERICK	PART/DOC. NO. 3647135-100	FSC 1410	NIIN 01-253-8073	NALC PD63
-------------------	---	-------------------------------------	--------------------	----------------------------	---------------------

EI CNTRL NO:

PROB BRIEF : GUIDANCE AND CONTROL SECTION FAILURE, NO VIDEO

PROBLEM DESCRIPTION : This problem addresses incidents in which MAVERICK Guidance and Control Sections failed MTS testing for Video related failure codes.

PREVENTIVE ACTION : There is no preventive action.

CORRECTIVE ACTION : No corrective action can be contemplated until Depot repair data is available at which time NAWCWPNS will review all available data.

OCCURRENCES:	SOURCE	TYPE	DOCUMENT NO.	DATE	DR STATUS
	VFA-115	CODR	R09604-01-0001	02JAN01	CLOSED
	VS-31	CODR	V09572-00-0015	20OCT00	CLOSED
	NOC FALLBROOK	PQDR II	N00396-95-0002	13FEB95	CLOSED *
	NOC FALLBROOK	PQDR II	N00396-95-0003	13FEB95	CLOSED *
	NOC FALLBROOK	PQDR II	N00396-94-0120	17OCT94	CLOSED *
	NWS YORKTOWN	PQDR II	N00109-94-3094	17MAY94	CLOSED *
	NWS YORKTOWN	PQDR II	N00109-94-3075	05MAY94	CLOSED *
	NWS YORKTOWN	PQDR II	N00109-94-3076	05MAY94	CLOSED *

* ACTION REPORTED IN PREVIOUS PUBLICATION

ACTION :	VFA-115	CODR	R09604-01-0001	02JAN01	CLOSED
-----------------	---------	------	----------------	---------	--------

END ITEM :	PART/DOC. NO. 3647135-100	FSC 1410	NIIN 01-253-8073	NALC PD63
	NOMEN: GUIDED MISSILE, MAVERICK			
	S/N: 6101343			
FAILED PART:	3647135-100	1410	01-253-8073	PD63
	NOMEN: GUIDED MISSILE, MAVERICK			

DESCRIPTION:

28DEC01: VFA-115 reported that weapon failed post load video check. Weapon moved to next known good station with identical result. Weapon loaded on VFA-113 aircraft with identical post load video check failure. Turned into USS Abraham Lincoln weapons department awaiting disposition instructions.

ACTION TAKEN:

12FEB01: NAWC Pt Mugu requested USS Abraham Lincoln weapons department to place missile in condition code "F" and ship to NWS Falbrook, CA for repair. This is closing action.

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 15694

(Continued)

ACTION : **ACTIVITY/CODE** **ASSIGNMENT** **DUE DATE STATUS**
SUMMARY NAWC PT MUGU/311000E REVIEW DEFICIENCY COMPLETE 12FEB01

REFERENCES : **IDENTIFICATION** **REFERENCE BRIEF**
VFA-115 MESSAGE 021855ZJAN01 PROBLEM REPORT
NAWC PT MUGU/311000E MESSAGE REPLY/CLOSING
120029ZFEB01

ACTION : **VS-31** **CODR** **V09572-00-0015** **20OCT00 CLOSED**

END ITEM : **PART/DOC. NO.** **FSC** **NIIN** **NALC**
S/N: 6100501
FAILED PART: 3647136-100 6920 01-254-7577 PY15
NOMEN: GUIDED MISSILE, MAVERICK

DESCRIPTION:
11OCT00: NAWC Pt. Mugu reported missile transmitted a weak video display during flight. Also, during flight the video tape recorder would not record. Missile turned into NAS Jacksonville weapons department awaiting disposition.

ACTION TAKEN:
24OCT00: NAWC Pt. Mugu requested that NAS Jacksonville weapons department place missile in condition code "F" and ship to NWS Fallbrook, CA for repair. This is closing action.

ACTION : **ACTIVITY/CODE** **ASSIGNMENT** **DUE DATE STATUS**
SUMMARY NAWC PT MUGU/311000E REVIEW DEFICIENCY COMPLETE 24OCT00

REFERENCES : **IDENTIFICATION** **REFERENCE BRIEF**
VS-31 MESSAGE 201535ZOCT00 PROBLEM REPORT
NAWC PT MUGU/311000E MESSAGE REPLY/CLOSING
240229ZOCT00

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 16229 CLOSED

	NOMENCLATURE	PART/DOC. NO.	FSC	NIIN	NALC
END ITEM :	GUIDED MISSILE, MAVERICK	3384304-101	1410	01-158-2872	PB69
	GUIDED MISSILE, MAVERICK	3647135-100	1410	01-253-8073	PD63

EI CNTRL NO:

PROB BRIEF : LEAKING FLUID FROM HYDRAULIC ACTUATION SYSTEM

PROBLEM : Hydraulic fluid leaking from hydraulic actuation system.
DESCRIPTION

PREVENTIVE : There is no preventive action at this time.
ACTION

CORRECTIVE : There is no corrective action at this time.
ACTION

	SOURCE	TYPE	DOCUMENT NO.	DATE	DR STATUS
OCCURRENCES:	NSF DIEGO GARCIA	CODR	N68539-00-0013	08NOV00	CLOSED
	NAS FALLON	CODR	N60495-00-0004	13JUN00	CLOSED *
	USS CONSTELLATION (CV-64)	CODR	R03364-99-0003	28AUG99	CLOSED *
	NAS FALLON	CODR	N60495-96-0003	21OCT96	CLOSED *

* ACTION REPORTED IN PREVIOUS PUBLICATION

ACTION : NSF DIEGO GARCIA CODR N68539-00-0013 08NOV00 CLOSED

	PART/DOC. NO.	FSC	NIIN	NALC
END ITEM :	3647135-100	1410	01-253-8073	PD63
	NOMEN: GUIDED MISSILE, MAVERICK			
	S/N: 6100168			
FAILED PART:	3647135-100	1410	01-253-8073	PD63
	NOMEN: GUIDED MISSILE, MAVERICK			

DESCRIPTION:

17OCT00: NAVSUPPFAC Diego Garcia reported that while conducting post flight inspection, load team leader discovered hydraulic fluid leaking from hydraulic actuation system of missile. Asset currently held on board the USS Camden, awaiting disposition instructions.

ACTION TAKEN:

27NOV00: NAWC Pt. Mugu requested place missile in condition code "F" and ship to NWS Fallbrook, CA for repair. This is closing action.

ACTION SUMMARY	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
	NAWC PT MUGU/311000E	REVIEW DEFICIENCY		COMPLETE 27NOV00

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 16229

(Continued)

REFERENCES :	IDENTIFICATION	REFERENCE BRIEF
	NSF DIEGO GARCIA MESSAGE 080019ZNOV00	PROBLEM REPORT
	NAWC PT MUGU/311000E MESSAGE	REPLY/CLOSING
	270229ZNOV00	

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 16251 CLOSED

END ITEM : NOMENCLATURE PART/DOC. NO. FSC NIIN NALC
GUIDED MISSILE, MAVERICK 3647136-100 6920 01-254-7577 PY15

EI CNTRL NO:

PROB BRIEF : NO DISPLAY SYMBOLOGY

PROBLEM : No display symbology or missile video was presented.
DESCRIPTION

PREVENTIVE : There is no preventive action at this time.
ACTION

CORRECTIVE : There is no corrective action at this time.
ACTION

OCCURRENCES:	SOURCE	TYPE	DOCUMENT NO.	DATE	DR STATUS
	VFA-15	CODR	V09015-01-0061	17SEP01	CLOSED
	VMA-211	CODR	M09412-00-0001	25JAN00	CANCELED*
	VS-22	CODR	V09287-96-0038	03JAN97	CLOSED *

* ACTION REPORTED IN PREVIOUS PUBLICATION

ACTION : VFA-15 CODR V09015-01-0061 17SEP01 CLOSED

END ITEM :	PART/DOC. NO.	FSC	NIIN	NALC
S/N: 5101101				
FAILED PART:	3384304-101	1410	01-158-2872	PB69
NOMEN:	GUIDED MISSILE, MAVERICK			

DESCRIPTION:
11SEP01: VFA-15 reported that pilot did not get weapon symbology in display. Upon recovery, weapon failure was verified by ground crew and down loaded. Release system check was performed without discrepancy. Weapons turned into USS Enterprise weapons department, awaiting disposition instructions.

ACTION TAKEN:
19SEP01: NAWC Pt. Mugu requested USS Enterprise weapons department to place missile in condition code "F" and ship to NWS Fallbrook, CA for repair. This is closing action.

ACTION SUMMARY	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
	NAWC PT MUGU/311000E	REVIEW DISCREPANCY		COMPLETE 19SEP01

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 16251

(Continued) |

REFERENCES : IDENTIFICATION

VFA-15 MESSAGE 171850ZSEP01
NAWC PT MUGU/311000E MESSAGE
190529ZSEP01

REFERENCE BRIEF

PROBLEM REPORT
REPLY/CLOSING

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 16304 CLOSED

END ITEM : NOMENCLATURE PART/DOC. NO. FSC NIIN NALC
GUIDED MISSILE, MAVERICK 3647136-100 6920 01-254-7577 PY15

EI CNTRL NO:

PROB BRIEF : FAILED IN FLIGHT

PROBLEM : Missile failed during flight.
DESCRIPTION

PREVENTIVE : There is no preventive action at this time.
ACTION

CORRECTIVE : There is no corrective action at this time.
ACTION

OCCURRENCES:	SOURCE	TYPE	DOCUMENT NO.	DATE	DR STATUS
	VFA-27	CODR	R65185-00-0042	29OCT00	CLOSED
	VFA-15	CODR	V09015-99-0070	04AUG99	CLOSED *
	VFA-87	CODR	V63922-99-0030	03AUG99	CLOSED *
	VFA-195	CODR	R09706-97-0015	17MAY97	CLOSED *

* ACTION REPORTED IN PREVIOUS PUBLICATION

ACTION : VFA-27 CODR R65185-00-0042 29OCT00 CLOSED

END ITEM : PART/DOC. NO. FSC NIIN NALC
3647136-100 6920 01-254-7577 PY15

NOMEN: GUIDED MISSILE, MAVERICK
S/N: 6101179
LOT: N/A

FAILED PART: 3647136-100 6920 01-254-7577 PY15
NOMEN: GUIDED MISSILE, MAVERICK
S/N: 6101179
LOT: N/A

DESCRIPTION:

25OCT00: VFA-27 reported while in flight, pilot selected weapon and displayed weapons degrade. Weapon failed to function. Weapon was down loaded and release and control system checked with no discrepancies. Weapon was loaded and tested on two additional aircraft with no discrepancies.

ACTION TAKEN:

06NOV00: NAWC Pt. Mugu stated problems would indicate an aircraft problem and not a missile failure. Request originator cancel deficiency report.

**MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM**

PROBLEM NO: 16304

(Continued)

09NOV00: This was a correction to original deficiency sent by VFA-27 requesting that a paragraph be changed to read "Missile tested on two additional aircraft with original in flight discrepancy". While in flight, pilot selected weapon and displayed weapons degrade. Weapon failed to function. Weapon was down loaded and ground crew performed release and control checks on affected aircraft with zero discrepancies on aircraft. Weapon was loaded and tested on two additional aircraft with original in flight discrepancy.

27NOV00: NAWC Pt. Mugu reported that original deficiency be cancelled due to the statement "Missile tested on two additional aircraft with no discrepancies". This would indicate an aircraft problem. For USS Kitty Hawk request place missile in condition code "F" and ship to NWS Fallbrook , CA for repair. This is closing action.

ACTION	:	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
SUMMARY		NAWC PT MUGU/311000E	REVIEW DEFICIENCY		COMPLETE 06NOV00
REFERENCES	:	IDENTIFICATION		REFERENCE BRIEF	
		VFA-27 MESSAGE 291200ZOCT00		PROBLEM REPORT	
		NAWC PT MUGU/311000E MESSAGE 060629ZNOV00		PROBLEM REPORT CLARIFICATION REQUEST	
		VFA-27 MESSAGE 090600ZNOV00		PROBLEM REPORT CORRECTION	
		NAWC PT MUGU/311000E MESSAGE 270329ZNOV00		REPLY/CLOSING	

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 16382 CLOSED

	NOMENCLATURE	PART/DOC. NO.	FSC	NIIN	NALC
END ITEM :	GUIDED MISSILE, MAVERICK	3384304-101	1410	01-158-2872	PB69

EI CNTRL NO:

PROB BRIEF : MISSILE FAILED TO DETONATE

PROBLEM : Missile was launched successfully but failed to detonate on impact
DESCRIPTION of target.

PREVENTIVE : There is no preventive action at this time.
ACTION

CORRECTIVE : There is no corrective action at this time.
ACTION

	SOURCE	TYPE	DOCUMENT NO.	DATE	DR STATUS
OCCURRENCES:	VFA-86	CODR	V09943-01-0015	22MAY01	CLOSED
	VP-26	CODR	V09610-97-0035	15DEC97	CLOSED *

* ACTION REPORTED IN PREVIOUS PUBLICATION

ACTION :	VFA-86	CODR	V09943-01-0015	22MAY01	CLOSED
----------	--------	------	----------------	---------	--------

	PART/DOC. NO.	FSC	NIIN	NALC
END ITEM :	3384304-101	1410	01-158-2872	PB69
	NOMEN: GUIDED MISSILE, MAVERICK			
	S/N: 5101189			
FAILED PART:	3384304-101	1410	01-158-2872	PB69
	NOMEN: GUIDED MISSILE, MAVERICK			

DESCRIPTION:

18MAR01: VFA-86 original deficiency reported missile properly guided to designated target but warhead did not detonate upon impact.

ACTION TAKEN:

30APR01: NAWC Pt. Mugu requested VFA-86 cancel original deficiency report and resubmit a more complete report required in order to process and track.

22MAY01: VFA-86 resubmitted a more complete deficiency report. Weapon acquired and locked on to laser energy prelaunch. Post fox, weapon properly guided to designated target but warhead did not detonate upon impact.

04JUN01: NAWC Pt. Mugu states that due to a phoncon between NAWC and VFA-86, their original deficiency report is cancelled. Retransmittal of cancellation message is not required.

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 16382

(Continued)

04JUN01: NAWC Pt. Mugu acknowledges receipt of problem which has been entered for tracking purposes only. This is closing action.

ACTION	:	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
SUMMARY	:	NAWC PT MUGU/311000E	REVIEW DEFICIENCY		COMPLETE 04JUN01

REFERENCES	:	IDENTIFICATION	REFERENCE BRIEF
	:	VFA-86 MESSAGE 191201ZAPR01	PROBLEM REPORT
	:	NAWC PT MUGU/311000E MESSAGE 300429ZAPR01	CORRECTED COPY PROBLEM REPORT REQUEST
	:	VFA-86 MESSAGE 220951ZMAY01	CORRECTED PROBLEM REPORT
	:	NAWC PT MUGU/311000E MESSAGE 040229ZJUN01	REPLY/CLOSING
	:	NAWC PT MUGU/321200E MESSAGE 040029ZJUN01	ORIGINAL REPORT CANCELLATION

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 16462 CLOSED

EI CNTRL NO:

PROB BRIEF : MISSILE JETTISONED DUE TO USAFE LANDING GEAR ON F-18

PROBLEM : This problem is created by any unsafe condition that may exist on an
DESCRIPTION aircraft that requires the jettison of the missile.

PREVENTIVE : There is no preventive action for this problem.
ACTION

CORRECTIVE : There is no corrective action for this problem.
ACTION

	SOURCE	TYPE	DOCUMENT NO.	DATE	DR STATUS
OCCURRENCES:	VP-16	CODR	V09229-01-0002	23JAN01	CLOSED
	VMA-311	CODR	M09416-99-0037	01JUN99	CLOSED *
	VFA-81	EMR	V09221-98-0044A	03SEP98	CLOSED *

* ACTION REPORTED IN PREVIOUS PUBLICATION

ACTION : VP-16 CODR V09229-01-0002 23JAN01 CLOSED

END ITEM : PART/DOC. NO. FSC NIIN NALC

S/N: 6101041

LOT: N/A

FAILED PART: 3647135-100 1410 01-253-8073 PD63

NOMEN: GUIDED MISSILE, MAVERICK

DESCRIPTION:

22JAN01: During an attempt launch an AGM-65Fmissile, the motor ignited and missile remained on the launcher. The missile was jettison due to unknown security of weapon launcher.

ACTION TAKEN:

26JAN01: NAWC Pt. Mugu reported an investigation cannot be conducted because the missile was jettisoned. It is suspected that there was a problem with the launcher, possible corrosion on the missile restraint device pin. Research is being conducted to determine the criteria, if required, for landing with missile aboard vice jettisoning. This is closing action.

ACTION SUMMARY	ACTIVITY/CODE	ASSIGNMENT	DUE DATE	STATUS
	NAWC PT MUGU/311000E	REVIEW DEFICIENCY		COMPLETE 25JAN01

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 16462

(Continued) |

REFERENCES : IDENTIFICATION

VP-16 MESSAGE 231600ZJAN01
NAWC PT MUGU/311000E MESSAGE
260029ZJAN01

REFERENCE BRIEF

PROBLEM REPORT
REPLY/CLOSING

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 16742 CLOSED

EI CNTRL NO:

PROB BRIEF : HYDRAULIC ACTUATOR FILL INDICATOR SERVICING

PROBLEM : Hydraulic actuation system fill indicator protruding beyond
DESCRIPTION reservoir module.

PREVENTIVE : Perform normal inspections of the missile hydraulic unit.
ACTION

CORRECTIVE : Ensure missile is serviced in accordance with the AW-820CE-MIB-020
ACTION maintenance manual.

OCCURRENCES:	SOURCE	TYPE	DOCUMENT NO.	DATE	DR STATUS
	USS KITTY HAWK (CV-63)	CODR	R03363-01-0024	02JUN01	CLOSED
	USS KITTY HAWK (CV-63)	CODR	R03363-01-0008	09MAR01	CLOSED
	USS KITTY HAWK (CV-63)	CODR	R03363-00-0029	30APR00	CLOSED *
	MAWTS-1	CODR	M55167-00-0006	28MAR00	CLOSED *

* ACTION REPORTED IN PREVIOUS PUBLICATION

ACTION : USS KITTY HAWK CODR R03363-01-0024 02JUN01 CLOSED
(CV-63)

END ITEM :	PART/DOC. NO.	FSC	NIIN	NALC
	S/N: 500036			
FAILED PART:	3384304	1410	01-158-2872	
	S/N: 500036			

DESCRIPTION:

31MAY01: USS Kitty Hawk reported missile hydraulic fill indicator was intruding beyond accumulator reservoir module on the missile. Attempts to push the indicator back in using a wood dowel and approximately 15 PSE pressure failed. Weapon was canned and place in condition code "J" awaiting disposition.

ACTION TAKEN:

04JUN01: NAWC Pt. Mugu requested that the missile be placed in condition code "F" and shipped to Fallbrook, CA for repair. This is closing action.

ACTION : ACTIVITY/CODE ASSIGNMENT DUE DATE STATUS
SUMMARY NAWC PT MUGU/311000E REVIEW DEFICIENCY COMPLETE 04JUN01

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 16742

(Continued)

REFERENCES :	IDENTIFICATION	REFERENCE BRIEF
	USS KITTY HAWK (CV-63) MESSAGE	PROBLEM REPORT
	020015ZJUN01	
	NAWC PT MUGU/311000E MESSAGE	REPLY/CLOSING
	040629ZJUN01	

ACTION : USS KITTY HAWK CODR R03363-01-0008 09MAR01 CLOSED
(CV-63)

	PART/DOC. NO.	FSC	NIIN	NALC
END ITEM :	S/N: 500038, 5100240, 5100141			
FAILED PART:	3384304-101	1410	01-158-2872	PB69
	NOMEN: GUIDED MISSILE, MAVERICK			

DESCRIPTION:
07MAR01: USS Kitty Hawk reported three missiles to have hydraulic fill indicators intruding beyond accumulator reservoir module.

ACTION TAKEN:
17APR01: NAWC Pt. Mugu requested missiles be placed in condition code "F" and shipped to NWS Fallbrook, CA for repair. This is closing action.

ACTION :	ACTIVITY/CODE	ASSIGNMENT	DUE DATE STATUS
SUMMARY	NAWC PT MUGU/311000E	REVIEW DEFICIENCY	COMPLETE 17APR01

REFERENCES :	IDENTIFICATION	REFERENCE BRIEF
	USS KITTY HAWK (CV-63) MESSAGE	PROBLEM REPORT
	090215ZMAR01	
	NAWC PT MUGU/311200E MESSAGE	REPLY/CLOSING
	170129ZAPR01	

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 16868 CLOSED

EI CNTRL NO:

PROB BRIEF : MISSILE BROKE LOCK ON LAUNCH

PROBLEM : Missile seeker broke lock on launch.
DESCRIPTION

PREVENTIVE : There is no preventative action at this time.
ACTION

CORRECTIVE : There is no corrective action at this time.
ACTION

	SOURCE	TYPE	DOCUMENT NO.	DATE	DR STATUS
OCCURRENCES:	VS-24	CODR	V09629-00-0031	14SEP00	CLOSED

ACTION :	VS-24	CODR	V09629-00-0031	14SEP00	CLOSED
----------	-------	------	----------------	---------	--------

	PART/DOC. NO.	FSC	NIIN	NALC
END ITEM :	S/N: 6101458			
FAILED PART:	3647135-100	1410	01-253-8073	PD63
	NOMEN: GUIDED MISSILE, MAVERICK			

DESCRIPTION:
11SEP00: VS-24 reported missile seeker apparently broke lock on launch. Missile impacted water approximately 1.5 meters north of target. Missile went high order on impact.

ACTION TAKEN:
26SEP00: NAWC Pt. Mugu stated cause for missile failure is unknown at this time. Without a missile firing report to analyze it will be hard to determine cause of this failure. This problem entered for tracking purposes only. This is closing action.

ACTION :	ACTIVITY/CODE	ASSIGNMENT	DUE DATE STATUS
SUMMARY	NAWC PT MUGU/311000E	REVIEW DEFICIENCY	COMPLETE 26SEP00

REFERENCES :	IDENTIFICATION	REFERENCE BRIEF
	VS-24 MESSAGE 141202ZSEP00	PROBLEM REPORT
	NAWC PT MUGU/311000E MESSAGE	REPLY/CLOSING
	261729ZSEP00	

30-NOV-01

MAVERICK ACTIVE
AIRBORNE WEAPONS CORRECTIVE ACTION PROGRAM

PROBLEM NO: 16897 CLOSED

END ITEM : NOMENCLATURE PART/DOC. NO. FSC NIIN NALC
GUIDED MISSILE, TRAINING 3384305-100 6290 01-254-7577 3W70

EI CNTRL NO:

PROB BRIEF : BRACKET FOR UMBILICAL CONNECTION BROKEN

PROBLEM : Upon conducting weapon inspection on missile, it was noticed that
DESCRIPTION the bracket that holds umbilical connection was broken on both sides
of umbilical connector.

PREVENTIVE : There is no preventative action at this time.
ACTION

CORRECTIVE : There is no corrective action for this problem.
ACTION

OCCURRENCES: SOURCE TYPE DOCUMENT NO. DATE DR STATUS
MALS-31 CODR M09131-00-0072 13JUL00 CLOSED

ACTION : MALS-31 CODR M09131-00-0072 13JUL00 CLOSED

END ITEM : PART/DOC. NO. FSC NIIN NALC
3384305-100 6290 01-254-7577 3W70
NOMEN: GUIDED MISSILE, TRAINING
S/N: 5000435
LOT: N/A
FAILED PART: 3384305-100 6290 01-254-7577 3W70
NOMEN: GUIDED MISSILE, TRAINING

DESCRIPTION:
16JUN00: MALS-31 reported that upon conducting weapon inspection of
missile, team member noticed bracket that holds umbilical connection
was broken on both sides of umbilical connector.

ACTION TAKEN:
06DEC00: NAWC Pt. Mugu requested that MALS-31 place missile in
condition code "F" and ship to NWS Fallbrook, CA for repair. This is
closing action.

ACTION : ACTIVITY/CODE ASSIGNMENT DUE DATE STATUS
SUMMARY NAWC PT MUGU/311000E REVIEW DEFICIENCY COMPLETE 06DEC00

REFERENCES : IDENTIFICATION REFERENCE BRIEF
MALS-31 MESSAGE 131034ZJUL00 PROBLEM REPORT
NAWC PT MUGU/311000E MESSAGE REPLY/CLOSING
060029ZDEC00